



Roettele Industries, Inc.

MATERIAL SAFETY DATA SHEET		DATE ISSUED: March 1, 2024	
SECTION I – PRODUCT IDENTIFICATION			
CODE NUMBER PRODUCT TRADE NAME MANUFACTURER EMERGENCY TELEPHONE	60FKFDA ELASTOMER COMPOUND FLOUROELASTOMER, FKM, VITON ROETTELE INDUSTRIES, INC. 909-606-8252		
SECTION II – HAZARDOUS INGREDIENTS			
SEE ADJACENT NOTE	THIS PRODUCT IS CONSIDERED NON-HAZARDOUS AT AMBIENT TEMPERATURE (SEE SECTION IV) ARE BOUND (ENCAPSULATED) IN THE ELASTOMER MATRIX (SEE FOOTNOTE 1, SECTION 339, PAGE 3 HAZARD SUBSTANCE LIST)		
SECTION III – PHYSICAL PROPERTIES			
APPEARANCE SPECIFIC GRAVITY SOLUBILITY IN WATER EVAPORATION RATE VAPOR DENSITY HAZARD	SMOOTH FINISH, BLACK 1.86 INSOLUBLE NOT APPLICABLE NOT APPLICABLE NOT APPLICABLE	EVAPORATION RATE MELTING POINT BOILING POINT	NOT APPLICABLE NOT DETERMINED NOT APPLICABLE
SECTION IV – FIRE AND EXPLOSION HAZARD			
FLASH POINT FIRE POINT EXTINGUISHING MEDIA FIRE FIGHTING PROCEDURE	600 F NOT DETERMINED WATER / WATER SPRAY / CO2 / DRY CHEMICAL / FOAM PROTECTIVE CLOTHING, BREATHING APPARATUS. STANDARD PRECAUTIONS INDICATED FOR ORGANIC CHEMICAL FIRE.		
SECTION V – HEALTH HAZARD DATA			
OVER EXPOSURE RISK FROM EXPOSURE FIRST AID PROCEDURE NOTE	NOT APPLICABLE NONE-IF ALL SAFETY PRECAUTIONS ARE FOLLOWED. RECOMMEND USAGE OF PRESCRIBED SAFETY EQUIPMENT (SEE SECTION VIII BELOW) USE STANDARD CLEANING PROCEDURES – SOAP & WATER APPROVED EYEWASH ETC. – SEEK PROFESSIONAL MEDICAL HELP IF INGESTED. PRODUCT IS SOLID AND INGREDIENTS ARE BOUND AT AMBIENT TEMPERATURE. AVOID CONTACT AND BREATHING OF FUMES IF MATERIAL IS INCINERATED.		
SECTION VI – REACTIVITY DATA			
STABILITY INCOMPATIBILITY DECOMPOSITION HAZARDOUS POLYMERIZATION	STABLE AT AMBIENT TEMPERATURE NONE KNOWN NORMAL ORGANIC COMBUSTION PRODUCTS, CO2, CO, CARBON WATER, ETC. PRODUCTS NOT APPLICABLE		
SECTION VII – DISPOSAL			
PREPARATION DISPOSAL	SOLID – NONE REQUIRED – USE NORMAL WASTE CONTAINER HANDLE PER APPROPRIATE FEDERAL, STATE, AND LOCAL REGULATIONS		
SECTION VIII – SPECIAL HANDLING			
VENTILATION PROTECTIVE DEVICES WORK PRACTICES STORAGE	WORK AREA VENTILATION RECOMMENDED FOR ELEVATED TEMPERATURE OPERATION USE APPROPRIATE DEVICES TO AVOID FUMES OR SKIN CONTACT DURING ELEVATED TEMPERATURE OPERATIONS USE GOOD PERSONAL HYGIENE, WASH HANDS AND EXPOSED BODY PARTS AFTER ANY EXPOSURE AND AT SHIFT END INSIDE STORAGE AT AMBIENT TEMPERATURE RECOMMENDED		

Manufacturer of Precision Non-metallic Gaskets & Washers

15485 Dupont Avenue • Chino, California 91710 • Telephone (909) 606-8252 • Fax (909) 606-8253